

Installationsanleitung Netscale 48 Splice Tray

Installation guide Netscale 48 Splice Tray




021.xxxx

A - Scope of delivery / Lieferumfang



021.xxxx



B - Installation / Installation







021.xxxx



021.xxxx




C - Minicore Cable / Minicore-Kabel




D - Loose Tube

D1




D2 Insert fibers / Fasern einlegen




E - Splicing / Spleissen


E1 Mount splice holder / Spleishalter montieren




E2 Cut fibers / Fasern schneiden



E3 Splicing / Spleissen




E4 Mount cover / Deckel montieren




F – Accessories / Zubehör

F1 Splice Holder / Spleisshalter




090.7857 / 090.7857

F2 ACS



021.5577

F3 ACS



021.xxxx

F4 Cable Guide Kit NW7 (10m)



021.5580

Headquarters

Switzerland

Reichle & De-Massari AG

Binzstrasse 32

CHE-8620 Wetzikon

Telephone HQ +41 (0)44 933 81 11

Telefax HQ +41 (0)44 930 49 41

E-Mail hq@rdm.com

www.rdm.com

R&M

Please note:

This guide shows the best practices for installation **ONLY**. R&M expressly disclaims all liability for any damage to material, equipment, and for any injury or death. Legal health and safety regulations should have priority over best practices as shown in this guide. R&M does not guarantee this guide to be free of errors. Products included may vary from products shown. Please exercise caution.